

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Swan and Canning Rivers

Site Code	Managing Authority	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assessment Category (SAC)	SAC Key Factor	Min No. LGA Samples Required 2013-2014	SAC Status Comments	Provisional Classification	Provisional Colour
EV3/520	Swan	Middle Swan Reserve	2008-2013	114	1450	D	11536	520	High - F/up	Rainfall	5	Collect 10 rainfall samples (48 -72hrs after heavy rainfall)	Very poor	Red
EV3/519	Swan	Ray Marshall Park (First Ave)	2008-2013	89	490	C	24000	146	High - F/up	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Poor	Amber
EV3/548	Bassendean	Point Reserve (Nth Jetty)	2011-2013	41	740	D	692	204	High - F/up	Storm water	12	Provide DoH stormwater drain monitoring results	Very Poor	Red
EV3/522	Bassendean	Sandy Beach Reserve	2008-2013	89	420	C	5513	343	Moderate	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Poor	Red
EV3/523	Bayswater	Hind Reserve (Garratt Rd - Jetty)	2008-2013	64	80	B	116	48	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/541	Bayswater	East St Maylands Yacht Club	2008-2013	69	95	B	158	52	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/517	Belmont	Garvey Park (Faulteroy Ave)	2008-2013	68	380	C	2067	227	Moderate	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Poor	Red
EV3/538	Belmont	Belmont Park Beach (End Beach - Goodwood Pd)	2008-2013	67	125	B	167	62	Moderate	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/539	Belmont	Cracknell Park (Riversdale Rd)	2008-2013	65	80	B	102	48	Moderate	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/542	Canning	Shelly Beach (Near Drain)	2008-2013	70	170	B	17227	63	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/547	Canning	Clontarf Bay (Cadets)	2008-2013	62	280	C	398	109	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Amber

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Swan and Canning Rivers

Site Code	Managing Authority	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assessment Category (SAC)	SAC Key Factor	Min No. LGA Samples Required 2013-2014	SAC Status Comments	Provisional Classification	Provisional Colour
EV3/545	East Fremantle	Preston Point - John Tonkin Park	2007-2013	56	2	A	26	16	Outstanding		5	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/505	Melville	Bicton Baths	2008-2013	64	90	B	1523	32	Moderate - F/up	Storm water	12	Collect min 5-10 rainfall (24-48hrs) samples	Good	Green
EV3/507	Melville	Cunningham St (Applecross)	2008-2013	64	38	A	117	22	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/532	Melville	Point Walter (Kiosk)	2008-2013	63	85	B	184	47	Moderate - F/up	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/533	Melville	Point Walter (Boat Ramps)	2008-2013	64	28	A	71	28	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/534	Melville	Waylen Bay (Scout Hall)	2008-2013	60	24	A	71	21	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/540	Melville	Deep Water Point Beach (Near Jetty)	2008-2013	60	18	A	58	21	Moderate - F/up	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green
EV3/544	Mosman Park	Johnston Street - Hill Tce Beach	2008-2013	84	9	A	41	17	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/503	Peppermint Grove	Keane St Beach (50M S Irvine)	2008-2013	79	55	B	113	39	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/528	Subiaco	Hackett Dve Crawley (Kiosk, Jetty)	2008-2013	76	105	B	201	55	Moderate - F/up	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/530	Subiaco	Hackett Dve Crawley (Tree)	2008-2013	76	55	B	97	40	Moderate - F/up	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/543	Subiaco	Abrahams Reserve Beach	2008-2013	76	26	A	71	23	Moderate - F/up	Rainfall	12	Collect min 5-10 rainfall (24-48hrs) samples	Good (a)	Green

Recreational Waters Bacterial Water Quality Sampling Program Site Status Report October 2013: Swan and Canning Rivers

Site Code	Managing Authority	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assessment Category (SAC)	SAC Key Factor	Min No. LGA Samples Required 2013-2014	SAC Status Comments	Provisional Classification	Provisional Colour
PR3/022	Perth	Claisebrook	2011-2013	37	22	A	58	27	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
PR3/023	Perth	Trinity	2011-2013	37	320	C	775	145	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Amber
PR3/024	Perth	Point Fraser	2011-2013	37	185	B	189	75	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
PR3/025	Perth	Barrack Jetty	2011-2013	37	9	A	39	22	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
PR3/026	Perth	Mounts Bay Road	2011-2013	37	105	B	151	56	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/511	South Perth	Como Beach Jetty	2009-2013	57	2	A	16	12	Outstanding		5	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/512	South Perth	Narrows Bridge	2009-2013	74	330	C	22370	422	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/513	South Perth	Coode St South Perth	2009-2013	75	270	C	442	111	Moderate - F/up	Rainfall	12	Collect 10 rainfall (24-48hrs) samples	Good	Green
EV3/536	South Perth	Como Beach South	2009-2013	69	130	B	960	65	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/537	South Perth	Como Beach North	2009-2013	69	400	C	24000	225	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green
EV3/546	South Perth	South Perth (Esplanade Beach)	2009-2013	90	115	B	167	58	Outstanding		12	Provide DoH Sanitary Inspection Report	Not Available	Green